

Step1

▮ 0,26 ★ 0,47
 ↑ 13 ↔ 36 ↻



∅42 r 96 h 82

Step

▮ 0,26 ★ 0,47
 ↑ 13 ↔ 36



↔ 37 ↗ 37 r 96 h 82

Step-L

▮ 0,26 ★ 0,47
 ↑ 13 ↔ 36



↔ 44 ↗ 44 r 96 h 82

Step-HA

▮ 0,26 ★ 0,47
 ↑ 13 ↔ 36 ↻



∅42 r 79-96 h 65-82



Step1



Step



Step-HA



Step

Symbol keys:

Metal parts: Steel

Finishes: Chrome, epoxy

▮ Fabric requirement, m

★ Leather requirement, m²

↔ Width, cm ↻ Swivel included
 ↑ Height, cm Return mechanism on request
 ↗ Depth, cm